

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,346,711 B1  
APPLICATION NO. : 10/661723  
DATED : March 18, 2008  
INVENTOR(S) : Sandip Datta Roy and Kevin Moore

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 2, line 60, and ending with Column 2, line 63 should read:


The BIOS program executing on the processor reads a status register destination for the IDE drive and detects whether data read from the status register destination has a predefined value.

Column 10, line 35, and ending with Column 10, line 38 should read:

14. upon the data read from the status register destination not having the first predefined value, return a second indication that an IDE drive is connected to the intelligent drive electronics channel;

Signed and Sealed this

Twenty-second Day of July, 2008



JON W. DUDAS  
*Director of the United States Patent and Trademark Office*